

# **INSTRUCTION MANUAL**



**SFR**Solder Feeder for Robot

This manual corresponds to the following reference:

#### SFR-B

# **Packing List**

The following items are included:



Solder Feeder ..... 1 unit



Reel Support ..... 1 unit Ref. 0024561



Cable 3 m..... 1 unit Ref. 0024563



**Allen Key 1,5 mm** ......... 1 unit Ref. 0741610



**Allen Key 2,5 mm** ........ 1 unit Ref. 0012574



**Allen Key 3 mm** ......... 1 unit Ref. 0013609



Screws DIN 912 M4x65...... 2 units Ref. 0024552



Screws DIN 912 M4x20...... 2 units Ref. 0921890



Screws DIN 7991 M4x10...... 1 unit Ref. 0490180









**Spanner 10 mm.**..... 1 unit Ref. 0017631

Insulator ...... 1 unit Ref. 0024588

**Manual** ...... 1 unit Ref. 0024557

### **Features and Connections**

The SFR Solder Feeder for Robot works together with one of the different GSFR Guide Kits, available for various solder wire diameters, with or without solder wire perforation. GSFR Guide Kits are sold separately.







- LED Indicator:
- · Blue: device powered
- Green: device working
- Red blinking: error, no solder wire or device is blocked

### Connection

- The SFR unit can be connected to a PLC by a five-pin Communications Cable (Ref. 0020261).
- Connect the cables to the corresponding pins to match your PLC connection. To comunicate with a computer use a DB9 female connector.
- Download the Communication Protocol at www.jbctools.com



For detailed information about pin distribution see following table:



Pin Distribution		
Pin	Color	Description
1	Brown	Power supply input: 24Vdc (±5%). 1.5 A current required
2	White	Serial input: RS232 RX
3	Blue	Common reference: GND for RS232 and witch
4	Black	Switch input: 0V or 24V to start feeding. Leave it open to stop
5	Grey	Serial output: RS232 TX



# Assembly: GSFR\* Wheels to SFR


For this operation, disconnect the device, and take off the cover by pressing the tabs. Use the allen key and the spanner, provided with the SFR, to assemble the components shown below.

#### GSFR\* with Solder Wire Perforation

- Insert the Intermediate Nozzle until its collar rests against the housing and tighten the screw.
- 2. Assemble the Guide Wheel and tighten the screw. Attention: Always use the correct wheel set for each wire thickness.
- 3. Assemble the Blade first, then mount the Blade Clamp onto the same axis and tighten the screw. **Caution:** handle the blade carefully to avoid injury.
- **4.** Insert the Inlet Nozzle into the hole and tighten the screw.


#### GSFR\* without Solder Wire Perforation

- Insert the Intermediate Nozzle until its collar rests against the housing and tighten the screw
- 2. Assemble the Support Wheel and tighten the screw. **Attention:** Always use the correct wheel set for each wire thickness.
- **3.** Assemble the Traction Wheel onto the axis and tighten the screw.
- **4.** Insert the Inlet Nozzle into the hole and tighten the screw.



# Assembly: GSFR Tube to SFR\* and TRA\*

- 1. Assemble the SFR to the TRA with the screws.
- 2. Assemble the GSFR Guide Tube to the TRA and tighten the screw.
- 3. Assemble the Outlet Nozzle onto the Dispensing Tube.
- 4. Assemble the GSFR Bushing into the SFR hole and tighten the screw.
- 5. Finally attach the Reel Support to the SFR with its screw.







# Assembly: Reel support positions

The Reel Support can be installed both vertically and horizontally to match your preferences.


Unscrew the bolt using a 3mm allen key and set the Reel Support as desired. Tighteen the bolt to fix the Reel Support in its position.



# Reel Support horizontally assembled



# Assembly: SFR independent from TRA\*



If mounting SFR independently from TRA, the Electrical Insulator is required.

Assemble the Insulator to your device with the screws (ref. 092890), and then the SFR to the Isolator with its screws (ref. 0014954).

The Electrical Insulator must be assembled to ensure a that the SFR work properly.



Do not use the SFR without insulator if it is mounted without the TRA.

\*Not included, sold separately




# Solder Wire Loading

The GSFR must be assembled previously.


- 1. Feed the Solder Wire into the Inlet Nozzle until it reaches the wheels.
- 2. Make sure the wire passes through the Intermediate Nozzle and enters into the Guide Tube.

**Important:** Set the wire thickness parameter before starting to dispense wire. To set W-THI Code see the Communication Protocol for SFR unit at **www.jbctools.com/jbcsoftware.html**.

Wire feeding is controlled by an external controller (Robot/PLC/Computer). See the Communication Protocol for SFR unit at www.jbctools.com/jbcsoftware.html




# **Dimensions (Vertical Reel Suport)**






# **Dimensions (Horizontal Reel Suport)**




### **Accessories**

### Guide Kit for SFR with Solder Wire Perforation

Ref. GSFRXXVLL





Guide kits are sold separately. Find JBC Guide kits at www.jbctools.com




### **Accessories**

## Guide Kit for SFR without Solder Wire Perforation


Ref. GSFRXXDLL





Guide kits are sold separately. Find JBC Guide kits at www.jbctools.com

# Components of the Soldering Unit



<sup>\*</sup>Not included, sold separately



### Maintenance

- Before carrying out maintenance, always unplug the tool and the device.
- Use a damp cloth to clean the Solder Feeder. Alcohol can only be used to clean the metal parts.
- Periodically check all cables and tube connections.
- Replace any defective or damaged parts. Use original JBC spare parts only.
- Repairs should only be performed by a JBC authorized technical service.

## Safety



It is imperative to follow safety guidelines to prevent electric shock, injury, fire or explosion.

- Do not use the device for any other purpose.
- Do not leave the appliance unattended when it is on.
- Be sure that the power supply is disconnected before changing any spare part.
- Avoid flux coming into contact with skin or eyes to prevent irritation.
- Be careful of fumes produced while soldering.
- Keep your workplace clean and tidy. Wear appropriate protective glasses and gloves while handling any component to avoid personal injury.
- Utmost care must be taken with liquid tin waste which can cause burns.

## **Specifications**

Solder Feeder

- Power Supply input: 24 Vdc (±5%). 1.5 A current required

- Ambient Operating Temp.: 10 - 50 °C / 50 - 122 °F

- Connections: M8-5 pin Commmunication Connector

Max. Speed: 120 mm/s / 4.72 in/s
Net Weight: 0.674 kg / 1.49 lb
Dimensions: see page 10 and 11

Reel Support

Spool capacity: up to 1 kg / 2.2 lb
Max Spool Diam.: 80 mm / 3.15 in
Max. Spool Height: 80 mm / 3.15 in
Net Weight: 0.130 kg / 0.29 lb

- Dimensions: see page 10 and 11

- Total Net Weight: 0.95 kg / 2.09 lb

- Total Package Dimension/Weight: 235 x 145 x 135 mm / 1.196 kg (L x W x H) 9.25 x 5.71 x 5.31 mm / 2.64 lb

Complies with CE Standards. ESD safe.



#### Warranty

JBC's 2 year warranty covers this equipment against all manufacturing defects, including the replacement of defective parts and labour.

Warranty does not cover product wear or misuse. In order for the warranty to be valid, equipment must be returned, postage paid, to the dealer where it was purchased.

Get 1 extra year JBC warranty by registering here: https://www.jbctools.com/productregistration/ within 30 days of purchase.



This product should not be thrown in the garbage.

In accordance with the European directive 2012/19/EU, electronic equipment at the end of its life must be collected and returned to an authorized recycling facility.

