

# www.jbctools.com

# **INSTRUCTION MANUAL**



# Auto-Feed Soldering Station Ref. AL-A


## **Packing List**

The following items are included:







## Features




## **Reel Stand Assembly**



## Adjusting System Assembly









4. Close the dragging mechanism.

5. Connect the handpiece to the station and switch it on. With the handpiece out of the stand, press the WIRE LOAD key till the solder leaves by the end of the guide tube.




## **Clutch Regulation**





## **Control Screen**




There are 4 tool status:

USE (Use). The tool is ready to work.

STD (Stand). The tool is placed in the stand but still not in the sleep mode.

- **SLP (Sleep).** The tool is in the sleep mode in the stand, its temperature has dropped till the sleep temperature.
- **OL.** The power circuit is overheated. The power is temporarily not supplied.




initial screen will be displayed.

#### Troubleshooting


Station troubleshooting available on the product page at www.jbctools.com

## Parameters Modification of the Tool and the Station

To enter into this mode, you must hold the SELECT key for 3 seconds.







## Maintenance

Before carrying out maintenance, always allow the equipment to cool.


- Clean the station screen with a glass cleaner or a damp cloth.
- Use a damp cloth to clean the casing and the tool. Alcohol can only be used to clean the metal parts.
- Periodically check that the metal parts of the tool and stand are clean so that the station can detect the tool status.
- Maintain tip surface clean and tinned prior to storage in order to avoid tip oxidation.
  Rusty and dirty surfaces reduce heat transfer to the solder joint.
- Periodically check all cables and tubes.



- Replace a blown fuse as follows:
- 1. Pull off the fuse holder and remove the fuse. If necessary use a tool to lever it off.



2. Press the new fuse into the fuse holder and replace it in the station.



- Replace any defective or damaged pieces. Use original JBC spare parts only.
- Repairs should only be performed by a JBC authorized technical service.



## Safety

## It is imperative to follow safety guidelines to prevent electric shock, injury, fire or explosion.

- Do not use the units for any purpose other than soldering or rework. Incorrect use may cause fire.
- The power cord must be plugged into approved bases. Be sure that it is properly grounded before use. When unplugging it, hold the plug, not the wire.
- Do not work on electrically live parts.
- The tool should be placed in the stand when not in use in order to activate the sleep mode. The soldering tip, the metal part of the tool and the stand may still be hot even when the station is turned off. Handle with care, including when adjusting the stand position.
- Do not leave the appliance unattended when it is on.
- Do not cover the ventilation grills. Heat can cause inflamable products to ignite.
- Avoid the contact of flux with skin or eyes to prevent irritation.
- Be careful with the fumes produced when soldering.
- Keep your workplace clean and tidy. Wear appropriate protection glasses and gloves when working to avoid personal harm.
- Utmost care must be taken with liquid tin waste which can cause burns.
- This appliance can be used by children over the age of eight and also persons with reduced physical, sensory or mental capabilities or lack of experience provided that they have been given adequate supervision or instruction concerning use of the appliance and understand the hazards involved. Children must not play with the appliance.
- Maintenance must not be carried out by children unless supervised.

## Specifications

AL-1A 120V 50/60Hz. Input fuse: 2A. Output: 23.5V AL-2A 230V 50/60Hz. Input fuse: 1A. Output: 23.5V AL-9A 100V 50/60Hz. Input fuse: 2A. Output: 23.5V

- Temperature Range:
- Output Peak Power:
- Tip to ground resistance:
- Tip to ground voltage:
- Ambient operating temp:
- Diameter of solder wire:
- Capacity of solder reels:
- Wire length:
- Speed:
- Control Unit Weight:
- Control Unit Dimensions:

Complies with CE standards. ESD protected.

90 - 450 °C (190 - 840 °F) 130W <2 ohms <2mV RMS 10 - 50 °C (50 - 122 °F) 0,4 - 1,8 mm (0.02 - 0.07 in) up to 2 Kg (4.41 lb) 1 - 60 mm (0.04 - 2.36 in) 30 mm/s (max) (1.18 in (max)) 5,8 Kg (12.9 lb) 195 x 200 x 240 mm (7.68 x 7.87 x 9.45 in)



#### Warranty

JBC's 2 year warranty covers this equipment against all manufacturing defects, including the replacement of defective parts and labour.

Warranty does not cover product wear or misuse. In order for the warranty to be valid, equipment must be returned, postage paid, to the dealer where it was purchased.

Get 1 extra year JBC warranty by registering here: https://www.jbctools.com/productregistration/ within 30 days of purchase.



This product should not be thrown in the garbage. In accordance with the European directive 2012/19/EU, electronic equipment at the end of its life must be collected and returned to an authorized recycling facility.



### www.jbctools.com

0020485-0120