

For more information **www.jbctools.com**

Solder Pot Cartridge



Safety



It is imperative to follow safety guidelines to prevent any damage.

- This cartridge needs the CT-SA Solder Pot Cartridge stand to avoid tipping accidentally.
- Allow to cool before handling.
- Do not use near flamable materials. Do not spill liquid over the solder pot.
- Do not melt "Cored Flux solder".
- Recommended temperatures for fine wires and lead free solder is 300°C. For thicker wires, increase the temperatures as necessary.
- While using this cartridge, glasses and protective gloves are mandatory.
- Turn off the station when not in use or not supervised.