



Firmware update for B-iRON soldering irons

Download the file.

Verify if folder "JBC" is present in internal storage in the Android device used as b.iron monitor. If do not exist créate it.

Copy downloaded file in JBC foder.

Access JBC B.iron APP



Select Update menu.



Select downloaded file and click "Update"

The screenshot shows the JBC web interface for tool ID 28714. The top navigation bar includes a menu icon, 'MENU', a home icon, 'Return to Work', the JBC logo, and the tool ID '28714'. The main content area is divided into three panels:

- Tool ID:** Displays '28714' in large blue text.
- Tool Information:** Shows '28714' at the top, followed by 'Hardware 0028383' and 'Software x886787'.
- Update File:** Contains a dropdown menu labeled 'Select your firmwan' and an 'Update' button. Both the dropdown and the button are circled in purple.

Process last about 5 minutes.

B.iron light continuously changes colour during the process.

Actualización firmware soldadores B-iRON

Descargar el archivo


En el almacenamiento interno de la Tablet usada como monitor del b.iron, verificar si existe la carpeta JBC. Si no existe crearla.

Copiar el archivo descargado en la carpeta JBC


Entrar en la APP JBC B.iron



Accede al menú Update.



Seleccionar el archivo descargado y pulsar "Update"



El proceso tarda aproximadamente 5 minutos.

La luz del b.iron cambia continuamente de color durante el proceso.