

POWER
INTERFACE
0814500

FUSE 5X20
T-1 A (230V)
T-2 A (120V-100V)

BLACK

BLACK

PCB TRANSFORMER
0004409 (230V)
0004410 (120V-100V)

TRANSFORMER
0003994 (230V-120V)
0004106 (100V)

PCB SECONDARY
TRANSFORMER
0004458

TOOLS CONNECTION

CONTROL
PCB AD 2950 /01
0003850

RESET
PASSWORD
0003415

CONNECTOR
0006627

GREEN-YELLOW

GREEN-YELLOW

GROUND
TERMINAL

BLUE

BLACK