Packing List



Desoldering	J Tip	10 u	nits
According to	nurchased reference*		

Manual 1 unit

Ref 0007419

Through Hole Desoldering*

Pad Cleaning*

- Ref. C36001 (Ø 0.6) - Ref. C36002 (Ø 0.8)
- Ref. C36003 (Ø 1.0)
- Ref. C36004 (Ø 1.2) - Ref. C36007 (Ø 1.4)
- Ref. C36006 (Ø 3.0)
- Ref. C36012 (Ø 0.8)
- Ref. C36014 (Ø 1.2)

- Ref. C36011 (Ø 0.6)

- Ref. C36013 (Ø 1.0)



C360 Tips

Micro Desoldering Tips for DR360


Tip care

The largest rod that fits in the tip hole should periodically be passed through in order to clean the intake tube.

The microdesoldering tips are protected against oxidization and wear.

Do not use abrasive tools which may damage the tips protective surface coating and avoid knocking them about.

To maintain the tips, use the recommended cleaning methods (brass wool, brushes, sponge). Only use the TT-A re-tinner when absolutely necessary.






www.jbctools.com



C360 Tip Ranges





		ØA		Ø	ØB		Ø max. pin	
	Ref.	mm	in	mm	in	mm	in	
Through hole desoldering	C36001	1.0	0.039	0.6	0.024	0.4	0.016	
	C36002	1.2	0.047	0.8	0.032	0.6	0.024	
	C36003	1.4	0.055	1.0	0.039	0.8	0.032	
	C36004	1.6	0.063	1.2	0.047	1.0	0.039	
	C36007	1.9	0.075	1.4	0.055	1.2	0.047	
	C36006	3.0	0.118	1.5	0.059	1.3	0.051	
Pad cleaning	C36011	1.0	0.039	0.6	0.024	-	-	
	C36012	1.3	0.051	0.8	0.032	-	-	
	C36013	1.4	0.055	1.0	0.039	-	-	
	C36014	1.6	0.063	1.2	0.047	-	-	